



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 9, 2010

Reviewed: 

Mine Name: Beef Hollow Quarry	Permit Number: S/035/0040
Operator Name: CMC Rock Products	Inspection Date: October 27, 2009
Inspector(s): L Heppler	Time: 7:00 am
Other Participants: none	Mine Status: Active


Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 2014 **Bond Amount:** \$25,200 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection.

Inspection Summary: Numerous stockpiles are in the area. Crushing equipment at the site has not been bonded for. Large Mine permit "Point West" NOI has yet to be completed. It appears that the disturbance is larger than 5 acres. Access road is not in the Beef Hollow NOI. There is no deleterious material on site. Every effort should be made to salvage top soil from the site prior to mining. Photos were taken to document site conditions.

Conclusions and Recommendations: Operator is to verify the disturbance at Beef Hollow is less than 5 acres as required for a small mine permit. Operator has 30 days to comply with all local, state and federal rules. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 





LAH:vs

cc: CMC Rock - Martin White

O:\M035-SaltLake\S0350040-BeefHollow\inspections\Insp-10272009.doc

06-09-2010



	
Access Road	Highwall
	
Crushing equipment	Crushing equipment and Stockpiles